

# ***R&R Services and Repairs, Inc.***

August 26, 2004

## News Brief

[www.data-collection.com](http://www.data-collection.com)

***Are your employees frustrated with the slot readers they are using because the readers are not reading or the magnetic or barcode badges are worn and don't work right?***

**If you answered "yes" to this question**

***We have your solution.***

A simple cost effective enhancement to a new or existing IBM 7526 DCT...

### **The 7526 RF Proximity Reader**

The system works by reading a micro chip on the employee badge which when placed near the reader will transmit a unique badge ID number. This ID number can be used with the IBM 7526 to link to an existing employee number or for other applications requiring specific employee identification i.e. payroll, access control or job tracking.

No more wasted time and money due to worn out or dirty employee ID badges and card readers. The 7526 RF Proximity reader will reduce multiple swiping, clocking time, employee and management frustration and most importantly will save money. To find out

more about the IBM 7526 and the Proximity Reader and what they can do for your data collection requirements call or E-mail us today.

## ***R&R Services and Repairs, Inc.***

***"Your Data Collection Connection"***

(561) 338-3264

[www.data-collection.com](http://www.data-collection.com)

*Thanks for your business!*

*Ron, Jack, Mike, Tottie & Ken*